DOIRC LATERAL LEARNING No: 01.05.01

CTU - Equipment Damage

INCIDENT

Coil brake not released results in movement of Track Stack towards Well Head.

FAILURE:

- Operating equipment without authority.
- Lack of supervision and communication of job responsibilities to CTU crew member.

LATERAL LEARNING:

- Assign mentor / supervisors for all crew members.
- Clearing assign job responsibilities and confirm employee understands.
- Tag out controls when supervisor is not present

