

DOIRC LATERAL LEARNING No: 01.06.03

Dropped 5' DP Stand

INCIDENT

Derrickman dropped stand of 5" DP across mast. Floor crew used air hoist to pull it back to monkey board. Air hoist cable too tight, lifted and dragged DP stand out thru V-door where it fell and punched hole in catwalk. No injuries, minor equipment damage.

FAILURE:

Retrieving dropped drill pipe stand from elevators.

LATERAL LEARNING:

- Toolbox talks are always necessary & useful.
- Stand must be properly secured before attempting to pul back with air hoist.
- Ensure all personnel cleared from rotary & catwalk areas.



