

Safety Alert

Use this Alert: Discuss in Tool Box Talks and HSE Meetings → Distribute to contractors → Post on HSE Notice Boards → Include in site HSE Induction

Over Head Lines (OHL) and Kicker Boards



During a recent Rig Move, several kicker board (KB) lines were lifted by crane, tele-handler (man riding basket) and persons climbing on the monkey board to lift the line clear of the rig mast.

- Do not lift Kicker Board lines
- Notify Electrical department when lines are too low

Safety Alert

Mr. Musleh asks the questions of can it happen to you?

1. Are the correct dimensions (width, height, length, weight) marked on equipment and briefed to drivers?
2. Is the height of the Rig confirmed during the Pre Rig Move Meetings ?
3. Are all kicker boards and OHL measured and recorded during the Route Survey?
4. Do you ensure the DSV or Tool Pusher present during Route Surveys?
5. Do you report inaccuracies of kicker board heights?
6. Are drivers reminded of overhead power lines during TBT's?
7. Do you ensure you adhere to the requirements of SP-1242?

