



## **ROAD TRAFFIC NEAR MISS**

### **INCIDENT**

**Logging truck/crew departed from WA Qarn Alam base to Rig 28 on 15/02/01 @ 11:30 hours. The truck/crew arrived at the rig site @ 19:46 hrs, 1 1/4 hours late against the journey plan. The delay involved an hour driving on the graded road from Marmul to Rahab ( 40Km).**

### **FAILURE:**

#### **Information error/omission.**

- Crew departed 40 minutes late against the journey plan.
- Crew took 15 minutes additional break against the journey plan.

#### **Inadequate planning.**

- Distance Qarn Alam - Rahab was taken from Drive Right Monitor as opposed to PDO Journey Management Map.

### **LATERAL LEARNING**

- Use PDO Journey Management Map information as guideline to calculate Journey distance / time.
- Allow extra "break" time in journey plan (minimum 15 minutes every 2 hrs of driving).
- Assure that Journey plan is calculated strictly to avoid night driving.
- STOP, report in time to Journey manager in case of potential night driving due to delay/ break down of vehicle(s).