

Rollover

INCIDENT

Rollover of Mitsubishi Pajero on graded road between Rig 26 & Camp, Thuleilat, Marmul.

FAILURE:

- Failure to follow rule, as driver swerved the vehicle instead of stopping as he sighted the stone.
- Observation
- He was unhurt because he had put on his seat belt and was driving well within the required speed limit.

LATERAL LEARNING:

- Follow the rules to prevent accident.
- Shortcuts must NOT be attempted.



Ashokan was unhurt because he put on his seat belt & was driving within the prescribed speed limits.