

Fire Incident at Marmul PDO Camp



On 24/12/09 at about 12:00 am a room occupant was awaken by rising temperature in his bed room. He opened the door and he was surprised by fire flame in the sitting room. Immediately he escaped from the room and alerted his neighbour who reported the fire to the emergency operator.



Immediate Cause


• Heat generated from hot plate which was kept next to a box of files.

Underlying Causes

- Non Compliance to house rules-No hot plate to be used in rooms.
- Poor house keeping
- Poor enforcement of rooms' safety and house keeping requirements
- Malfunction of Smoke detector did not work

Actions to stop recurrence

- Discussed the incident during area HSE meeting.
- OSO/8 to come up with a list of items or devices that shall not be allowed in the room –with regards to prevention of any type of fire incidence 31-02-2010
- OSO/81B/N/M to confiscate hot plates or other devices that could ignite fire that are found in the room.
- All area to keep track on offenders and any repeated case of non Compliance – i.e. any of the above items or devices found in the same room-Supervisor to issue a warning letter to the offenders.
- LSR (safety critical equipment) consequences should be applied to any individual who are found tempering with smoke detectors



 Non Production Facilities inspections (part of 2010 HSE Plan) should include Safety aspects as well. Area HSE Advisors to ensure the safety aspects are contained in the inspections check lists by 15-01-09