DOIRC LATERAL LEARNING No: 00.12.03

Fell From Work Platform

INCIDENT:

Restricted Work Case Incident - Halliburton Fahud Facility

FAILURE:

Lapse in concentration resulted in employee falling down work platform stairs. Sub-Standard design of stairs - narrow width

LATERAL LEARNING:

Prior to commencing <u>any</u> task STOP, identify and assess the hazards. Inconsistent design of stairs on work platforms.





Sustained cut below knee requiring 9 stitches



Correct stair design



In-Correct - Narrow width