

# MR. MUSLEH's NEWS



Welcome to issue No. 8 of *Mr. Musleh's News*, the communication which provides a 'one stop shop' for you to receive learnings from incidents in PDO and the Oil and Gas industry.

This month Mr. Musleh will summarise the learnings from incidents of the lost time injuries (LTIs) that have occurred during quarter 1 of 2016.

You can browse the incidents in the newsletter which have been designed to be read in an easy to digest format and delve deeper into the learning's if you think the incident or learning is relevant to you.

Please disseminate this bulletin to your teams and use it in your tool box talks, HSE meetings and notice boards.

## Index

- Don't take short cuts
- Unsecured ladder causes fall
- Are you aware of pinch points?
- Slips and falls
- Driller drops the joint
- Climber falls





### Don't take short cuts

A four man team was unloading a mobile cylinder trolley from a vehicle. As they placed it on the ground one of the team had his hand between the bottom of the trolley & the ground crushing his right hand little finger resulting in the tip being amputated.

[Link](#)



### Unsecured ladder causes fall

An electrician was climbing a ladder secured at the top by electrical tie wraps, the tie wrap snapped causing him to fall approximately 1.5m resulting in a cut to the inside of his right ankle and a fractured heel requiring surgery.


[Link](#)



### Pinch points, are you aware?

A roustabout was changing a mud pump liner. Whilst lifting the liner from the retainer inside the mud pump liner box, one hand slipped and the liner dropped down trapping his right index finger between the top of the retainer and the shoulder of the liner amputating the tip of his finger.

[Link](#)





### Slips and falls

Whilst descending from a Forklift Truck cabin, an operator slipped from the access ladder and fell to the ground landing on his right hand resulting in a fracture to his right wrist.


[Link](#)



### Driller drops the joint

After completion of BOP flushing, Driller and Floor hands broke out 5" pup joint. Driller lowered and tilted the elevator to unlatch pup joint. At the time driller lowered pup joint on Rig floor, Trainee Assistant Driller unlatched the elevator causing the pup joint to tilt on wear pushing and then bounced to floor man right foot resulting in a fracture of the right big toe.

[Link](#)



### Climber falls

A heavy vehicle driver was unlatching chains and boomers from a batch mixer on top of a flatbed trailer. He stepped to the side of the batch mixer pulling the chain and lost his balance falling on the ground injuring his left ankle.

[Link](#)

