MR. MUSLEH's NEWS

Welcome to issue No. 3 of *Mr. Musleh's News*, the communication which provides a 'one stop shop' for you to receive learnings from incidents in PDO and the oil and gas industry.

This month Mr. Musleh will summarise the learnings from incidents of the lost time injuries (LTIs) that have occurred during April 2015.

You can browse the incidents in the newsletter which have been designed to be read in an easy to digest format and delve deeper into the learning's if you think the incident or learning is relevant to you.

Please disseminate this bulletin to your teams and use it in your tool box talks, HSE meetings and notice boards.



Index

- Radiator fan fractures finger
- Finger amputated
- Chain binder damages eye
- Tongs fracture finger
- Kerb stone fractures shins
- Barrier fractures thumb



Volume: 1 Issue: 3





Radiator fan fractures finger

A welder was investigating a leak on a welding machine radiator while the machine was still running. While pointing to the area his finger came into contact with the moving fan.

Link






Finger amputated

Floorman traps finger between the slips and his steel toe cap causing amputation of his finger tip.

<u>Link</u>






Chain binder damages eye

A truck driver was using a chain binder with cheater bar to secure a load on his trailer. He pushed the lever down to lock it in place using a cheater bar but the chain binder had not fully locked and as he removed the cheater bar the lever under high tension swung up violently and hit him in the face causing severe injury to his right eye.

Link







Tongs fracture finger

While running in the hole the rig crew was changing the elevation of the manual tongs. A roustabout went to move the tongs so they would not hit the tubing elevator but in doing so his fingers became trapped between the elevator and tongs fracturing his finger.

Link





Kerb stone fractures shins

After crossing a road in camp, the camp manager tripped on the kerb stone landing badly fracturing both shins.

Link





Barrier fractures thumb

While offloading barrier posts the worker lost his grips and was hit by a falling post resulting in a deep cut and fracturing his thumb.

<u>Link</u>

