

MR. MUSLEH's NEWS



Welcome to issue No. 9 of *Mr. Musleh's News*, the communication which provides a 'one stop shop' for you to receive learnings from incidents in PDO and the oil and gas industry.

This month Mr. Musleh will summarise the learnings from incidents of the lost time injuries (LTIs) that have occurred during quarter two 2016.

You can browse the incidents in the newsletter which have been designed to be read in an easy to digest format and delve deeper into the learning's if you think the incident or learning is relevant to you.

Please disseminate this bulletin to your teams and use it in your tool box talks, HSE meetings and notice boards.

Index

- Finger pulled between belts
- Water breaks nose
- Choke line drops on derrick mans foot
- Driller falls 3.5m
- Mechanic crushed by vehicle
- Unauthorised Journey kills supervisor
- Safety Guard left open
- Fall from the stair
- Technician falls backwards
- Stored energy breaks bone
- Supervisor rolls over





Finger pulled between belts

An Electrician checking the belt tension on the wash gun unit. The mechanic, leaning on the unit caught the start button unintentionally; the rotary belt started to spin and pulled the electrician's fingers into the pulley.

[Link](#)



Water breaks nose

While on a team building day an employee suffers a broken nose when he fell off a banana boat into the sea.


[Link](#)



Choke line hose drops on Derrick mans foot

When they found the choke line hose (CLH) was stuck, the Night Tool Pusher instructed the floor man to collect a pry bar. While waiting for the pry bar, the derrick man tried to release the CLH, using a sledge hammer. Result broken foot.

[Link](#)



Driller falls 3.5m

During Hoist Rig down the shade tilted when it was being lifted by a forklift knocking the driller off balance and falling from a height of 3.5 meters to the ground.

[Link](#)






Mechanic crushed by vehicle

Mechanics were working in the vehicle workshop area, upon completion of the job, the vehicle was started from the outside whilst still in gear driving forward crushing the second mechanic who was standing in front of the vehicle and in the “line of fire”.


[Link](#)



Unauthorised journey kills Supervisor

The driver had departed on a unauthorised journey from Nimr prior to working hours and without a journey plan.


[Link](#)



Safety guard left open

Trainee Night Tool Pusher was standing on top of the mud pump while it was running and the piston cover was open, he slipped, lost his balance and his foot went inside resulting in a fracture to his right foot.

[Link](#)



Fall from the stair

Stepping down diagonally from the landing, and tripping on the raised edge of the walkway and fell on his right hip.

[Link](#)






Technician falls backwards

Whilst loosening nuts on a flange using a ring spanner it slipped off the nut as the fabricator applied force to it, causing him to lose balance and fall to the ground fracturing his left wrist and right elbow.


[Link](#)



Stored Energy breaks bone

The roustabout attached the wire rope sling to the Top-drive but wasn't aware that it was twisted (and had stored energy), as he pulled the wire rope sling, the sling unwound and struck his hand fracturing a bone.

[Link](#)



Supervisor rolls over

A supervisor was driving to Qarn Alam from Muscat in a Company vehicle. During the journey he drifted off the road and oversteered in an attempt to regain control. The vehicle rolled over multiple times causing the driver's head to hit the side window frame resulting in his death.

[Link](#)

