

PDO Incident First Alert - Oman Shapoorji



Incident Type	LTI#02	Pattern	Struck By
Date / Time	18.01.2020@13:00hrs	Directorate	External Affairs – Value Creation
Location	RAH Project	Dept	EVR

Target Audience

Drilling, Operations, Engineering & Construction

What happened

A telehandler moved backwards striking the wall of the rest area, leading to the collapse of the wall which fell onto a mason who was resting inside the rest area.



Mr. Musleh asks the questions of can it happen to you?

1. Do you ensure Plant & Equipment is parked on level ground?
2. Do you ensure vehicle hand brake is applied and chocks in place?
3. Are you are aware of the site emergency plan when an incident occurs?



Please disseminate this LTI notification to your teams and use it in your tool box talks and HSE meetings and notice boards.



V 1 (2020)



شركة تنمية نفط عمان
Petroleum Development Oman